


## Ch-1

# Basic Machine Tools and Metal Cutting Principles



Subject:- MP  
Code:-3141908

Prepared by:  
Asst.Prof.Harin Prajapati  
(Mechanical Department,ACET)

# Basic Mechanics of Metal Cutting

- **Metal** ahead of the **cutting tool** is **compressed** and this results in the **deformation** or **elongation** of the **crystal structure** resulting in a **shearing** of the metal.
- As the **process continues**, the metal above the cutting edge is forced along the “chip-tool” interference zone and is moved away from the work.

# Basic Mechanics of Metal Cutting




FIGURE 21-13 Schematic representation of the material flow, i.e., the chip forming shear process.

# Chip Formations


- During this process three basic types of chips are formed namely:
  - Discontinuous
  - Continuous
  - Continuous with a Built-Up Edge (BUE)

# Discontinuous

- Typically associated with **brittle metals** like Cast Iron
- As **tool contacts work**, some **compression takes place**
- As the **chip starts up** the chip-tool interference zone, **increased stress occurs** until the metal reaches a **saturation point and fractures** off the work piece.


# Discontinuous

- Conditions which favor this type of chip
  - Brittle work material
  - Small rake angles on cutting tools
  - Coarse machining feeds
  - Low cutting speeds
  - Major disadvantage—could result in poor surface finish



# Continuous

- Continuous “ribbon” of metal that flows up the chip/tool zone.
- Usually considered the ideal condition for efficient cutting action.



# Continuous

- Conditions which favor this type of chip:
  - Ductile work
  - Fine feeds
  - Sharp cutting tools
  - Larger rake angles
  - High cutting speeds
  - Proper coolants




# Continuous with a Built-up Edge(BUE)

- Same process as continuous, but **as the metal begins to flow up** the chip-tool zone, small particles of the **metal begin to adhere or weld themselves to the edge** of the cutting tool.
- As the particles continue to weld to the tool it affects the cutting action of the tool.

# Continuous with a built-up edge(BUE)

- ▶ This type of chip is common in softer non-ferrous metals and low carbon steels.
- ▶ Problems
  - Welded edges break off and can become embedded in workpiece
  - Decreases tool life
  - Can result in poor surface finishes



# Heat & Temperature in Machining

- In **metal cutting** the **power input** into the process is largely **converted to heat**.
- This elevates the temperature of the chips, work-piece and tool.
- These elements along with the coolant act as heat sinks.
- So lets look at coolants...

# Coolants/Cutting fluids

- Cutting fluids are used extensively in metal removal processes and they
  - Act as a **coolant, lubricant**, and assist in **removal of chips**.
  - Primary **mission of cutting fluids** is to **extend tool life** by **keeping keep temperatures down**.
  - Most **effective coolant is water...**
  - However, it is hardly ever used by itself.
  - Typically **mixed with a water soluble oil** to add **corrosion resistance** and **add lubrication capabilities**.

# Issues Associated With Coolants

- Environmental Concerns
- Machine systems and Maintenance
- Operators Safety

# Machining Operations

- Machining Operations can be classified into two major categories:
  - Single point = Turning on a Lathe
  - Multiple tooth cutters = pocket milling on a vertical milling machine

# Tool Selection Factors

- Inputs
- Work material
- Type of Cut
- Part Geometry and Size
- Lot size
- Machinability data
- Quality needed
- Past experience of the decision maker

# Constraints

- Manufacturing Practice
- Machine Condition
- Finish part Requirements
- Work holding devices/Gigs
- Required Process Time

## Outputs

- Selected Tools
- Cutting parameters



# Tool Selection Process




FIGURE 22-2 The selection of the cutting tool material and geometry and the cutting conditions for a given application depends on many variables.

# Elements of an Effective Tool

- High Hardness
- Resistance to Abrasion and Wear
- Strength to resist bulk deformation
- Adequate thermal properties
- Consistent Tool life
- Correct Geometry

# Tool Materials

- Wide variety of materials and compositions are available to choose from when selecting a cutting tool
- We covered these in the previous chapter


# Tool Geometry


- The geometry of a cutting tool is determined by three factors:
  - Properties of the Tool material
  - Properties of the Work piece
  - Type of Cut

# Tool Geometry


- The most important geometry's to consider on a cutting tool are
  - Back Rake Angles
  - End Relief Angles
  - Side Relief Angles

# Standard Terminology for Tool Geometry





(a)



(b) Tool signature:  $\alpha_b$ ,  $\alpha_s$ , ERA, SRA, ECEA, SCEA, NR

# Rake Angles

- Back-Allows the tool to shear the work and form the chip.
- It can be positive or negative
  - Positive = reduced cutting forces, limited deflection of work, tool holder and machine
  - Negative = typically used to machine harder metals-heavy cuts
- The side and back rake angle combine to form the “true rake angle”



# Rake Angles

- Small to medium rake angles cause:
  - high compression
  - high tool forces
  - high friction
  - result = Thick—highly deformed—hot chips




# Rake Angles

- Problems....as we increase the angle:
  - Reduce strength of tool
  - Reduce the capacity of the tool to conduct heat away from the cutting edge.
  - To increase the strength of the tool and allow it to conduct heat better, in some tools, zero to negative rake angles are used.

# Negative Rake Tools

- ▶ Typical tool materials which utilize negative rakes are:
  - Carbide
  - Diamonds
  - Ceramics
- ▶ These materials tend to be much more brittle than HSS but they hold superior hardness at high temperatures.
- ▶ The negative rake angles transfer the cutting forces to the tool which help to provide added support to the cutting edge.

# Negative Rake Tools








# Summary Positive vs. Negative Rake Angles

- Positive rake angles
  - Reduced cutting forces
  - Smaller deflection of work, tool holder, and machine
  - Considered by some to be the most efficient way to cut metal
  - Creates large shear angle, reduced friction and heat
  - Allows chip to move freely up the chip-tool zone
  - Generally used for continuous cuts on ductile materials which are not too hard or brittle

# Summary Positive vs. Negative Rake Angles



- Negative rake angles
  - Initial shock of work to tool is on the face of the tool and not on the point or edge. This prolongs the life of the tool.
  - Higher cutting speeds/feeds can be employed

# SINGLE-POINT TOOL GEOMETRY





# MULTIPLE-CUTTING-EDGE TOOLS






FIGURE 22.17 Tool geometry elements of a four-tooth face milling cutter: (a) side view and (b) bottom view.






FIGURE 22.18 The broach: (a) terminology of the tooth geometry, and (b) a typical broach used for internal broaching.


# Tool Angle Application

- Factors to consider for tool angles
  - The hardness of the metal
  - Type of cutting operation
  - Material and shape of the cutting tool
  - The strength of the cutting edge

# Carbide Inset Selection



# Carbide Inset Selection



*M1-Fine  
M2-Medium  
M3-S.S  
M4-Cast iron  
M5-General Purpose*

A.N.S.I. Insert Identification System  
ANSI - B212.4-1986



**AMIRAJ**  
COLLEGE OF ENGINEERING & TECHNOLOGY