

### Assignment -7

1. Explain bending in sheet metal forming. Show various stresses in bending process.
2. Differentiate between Punching and Blanking operation in context of purpose, metal scrap, punch and die dimension.
3. By Slab Analysis for Sheet Drawing, Prove  $P=2K \cdot \sigma \cdot x$ . Write the assumptions.